

RECORD OF  
COMMUNICATION☒ PHONE CALL   ☐ DISCUSSION   ☐ FIELD TRIP   ☐ CONFERENCE  
☐ OTHER (SPECIFY)

(Record of item checked above)

TO: Daniel Chang  
Hawaii State Dept. of HealthFROM: Marvin Young  
EPA, Region 9

DATE 10/29/85

TIME

SUBJECT  
PA's - ABC Disposal Company, Kapaa Landfill, Hawaii Coast Processing

## SUMMARY OF COMMUNICATION

I called Daniel to discuss PA's which he prepared. I also spoke with Duke Frain, a geologist with the Dept. of Health. The information is as follows:

ABC Disposal Company. The site of concern is not a disposal facility or transfer station for waste materials. The location was used for parking and servicing vehicles used for transporting solid waste from places of business to solid waste disposal facilities. A drive-by inspection of the former site of operation revealed no reason to initiate further assessment activities.

Kapaa Landfill. Duke indicated that the landfill is located over a poor water-bearing formation. The nearest drinking water well is approximately 2 miles away in a direction perpendicular to the flow of ground water (which is toward the ocean, app. 2000 feet away). In addition, the landfill is located in an area where underground injection of waste is permitted under the State's UIC program due to the poor potential for development of ground water in that area.

Hilo Coast Processing. Daniel noted that PCB's, solvents, and other chemicals used in the processing plant were handled in a basically responsible fashion. Duke indicated that the facility did not overlie any ground waters of concern.

## CONCLUSIONS, ACTION TAKEN OR REQUIRED

## INFORMATION COPIES

TO: